

SOLDERING STATION PARTS LIST

This list of parts will apply to any version of this model, though adjustments will need to be made for any customization added.

- Laser or CNC cut panels
- (2) 3D-printed LocLine cradles
- 20 in length of 1/4 in LocLine
- (2) 3D-printed magnification/light holders
- 3 in diameter magnifying lens
- Headlamp light
- (6) #8-32 1/2 in machine screws
- (4) #8-32 1/2 in machine screws
- (10) #8-32 nuts

- (6) 1/8 in cable clamps
- (6) 6 in lengths of 1/8 in gooseneck
- Wood glue
- Super glue

